



## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re patent of

Attn: Certificate of

**Correction Branch** 

Kanji HATA et al.

:

Patent No. 6,935,017 B2

Atty Docket No. 2000 0351

Issued August 30, 2005

Confirmation No. 2898

COMPONENT MOUNTING APPARATUS HAVING COMPONENT SUPPLY TABLES PROVIDED ON OPPOSITE SIDES OF A COMPONENT TRANSFER PATH (as amended)

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:


In accordance with the provisions of 37 CFR 1.322, it is respectfully requested that a Certificate of Correction issue to correct the following:

#### **ON THE FRONT PAGE:**

In Item (56) References Cited:

Please insert --5,741,114 A 4/1998 Onodera ... 29/740--.

Certificate of Correction



# **REMARKS**

The error listed above apparently arose due to a PTO mistake. Accordingly, a Certificate of Correction should issue at no expense to patentees. Form PTO-1050 accompanies this request.

Respectfully submitted,

Kanji HATA et al.

Joseph M. Gorski

Registration No. 46,500 Attorney for Patentees

JMG/nka Washington, D.C. Telephone (202) 721-8200 Facsimile (202) 721-8250 August 21, 2006 To: The Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO

6,935,017 B2

DATED

August 30, 2005

INVENTOR(S)

Kanji HATA et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# **ON THE FRONT PAGE:**

# In Item (56) References Cited:

Please insert --5,741,114 A 4/1998 Onodera ... 29/740--.

Wenderoth, Lind & Ponack, L.L.P. 2033 K Street, N. W., Suite 800 Washington, D.C. 20006-1021

PATENT NO. 6,935,017 B2

No. of additional copies

